Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Development of park and playground at siddharthanagara in Ward No.16 RR Nagara zone
2	Administration Approval & Date	AC/RRN/AS/433/2012-13 Dtd.24-07-2012 by AC RRNZ
3	Technical Sanction Estimate No.& Date	CE/RRN/TS/16-4/12-13 dtd: 26-07-2012 by CE (RRN)
4	Estimate Amount	Rs.50.00 Lakhs + KRIDL Charges
5	Job Code No.	016-12-000045
6	P-Code	P-2274
7	Agreement No & date	EE/RRND/AG No./69/2012-13 Dtd.02-08-2012
8	Work order Number & Date	EE/RRND/W.O/69/2012-13 Dtd.02-08-2012
9	Contract Amount as per Agreement	Rs.50,00000/- Including KRIDL Charges
10	Bill Amount	Rs. 38,53,585/- Including KRIDL Charges
11	B.R. No. & Date	221 /13-14 Dtd.20-08-2014
12	Agency	KRIDL
13	M.B. Number & Page No. of Measurement recordes	2143/13-14 Pages 214234 to 214246
14	Date of Inspection	2/8/2015
15	Enclosures	1) Extract of MB No.2143 Page No.214246 2) 6 Number of photos taken during inspection
16	Inspection Report	The above Site was Inspected by me along with the Concerned officials. The measurement was checked by me and found to be Satisfactory

EE RR Nagara Division
ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು (ಯೋಜನೆ)
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

2/8/2015
(R.Sathyanarayana)
Inspection Report officer,

M.A.R. 57 (Rule 116)

Measurement Book

No. A/10 214246

Serial No.....

Name of work.....From.....To.....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8